



# frequently asked questions

---

## h1000 CND

---

### “How Do I Create Waypoints Manually on my CND”

**The procedure for adding Waypoints manually is as follows:**

1. With the unit switched ON, press the SETUP key and use the cursor keys to scroll to WAYPOINTS.
2. Press ENTER and select the CREATE ‘softkey’.
3. Using the cursor keys, scroll to the ‘Enter Position Manually’ option and press ENTER.
4. Scroll through the options, select ‘Name’, Press the ENTER key.
5. Alter the waypoint Name, Symbol, Latitude, Longitude or Colour by using the cursor keys and pressing the ENTER key to edit.
6. Press the ACCEPT ‘softkey to confirm your selections.
7. Your new waypoints will now appear in the waypoint list.

Press the CLEAR key twice to return to the chart view.